03



Stress measurement in high temperature environment

Spot-welding type strain gauges can measure stress in high temperature environments up to 800°C.

To install these strain gauges, we use Spot welder.





